



RECEIVED  
NOV 25 1994

November 22, 1994

OPE32451.S0.SD

Environmental Protection Agency  
1200 Sixth Avenue HW114  
Seattle, WA 98101

Attention: Monica Rolluda

Subject: Transmittal of Weyerhaeuser Report


Attached please find a copy of the *Independent Cleanup Action Report, Former No. 1 Cell Room Diffuser Removal* for the Weyerhaeuser Chlor-Alkali Plant located in Longview, Washington.

Figure 3 of the report shows sample locations before diffuser removal and Figure 5 shows sample locations after the diffuser removal. As indicated in Figure 5 of the report, sample location 6 included 1 standard sample and 1 replicate sample. The standard sample contained 7.2 mg/kg mercury while the replicate contained 0.5 mg/kg for an average mercury concentration of 3.85 mg/kg.

If you have questions or comments please call Jim Sims at 206/636-6343 or myself at 503/235-5000.

Sincerely,

CH2M HILL



John L. Childs, PE  
Project Engineer

c: Kevin Godbout/Weyerhaeuser w/o attachment  
Jim Sims/Weyerhaeuser w/o attachment  
Stu Brown/CH2M HILL w/o attachment

USEPA SF



1457540